



## View 6000 Release Notes

---

<b>MODELS:</b>	All
<b>VERSION:</b>	1.42 - replaces all previous versions
<b>PART #:</b>	365-7017
<b>COMPATIBILITY:</b>	All units
<b>NEW FEATURES:</b>	None
<b>CHANGES:</b>	NOTE: 25ns part at location U116 may behave like 15ns and the autodetection scheme may not work correctly. A new hidden command (RAMTYPE ) is created in order to force the CPU to treat the part as "Fast" or "Slow".
<b>CORRECTIONS:</b>	1. 1. Fixed incorrect YUV sequence during frame grab.
<b>KNOWN BUGS:</b>	None
<b>RELEASE DATE</b>	2 August 2001

---