



Release Notes

Product SuperView 1000 / 500 / *VGAplus*

VERSION: 5.42

COMPATIBILITY: This release can only be applied to SuperView 500/1000/VGAplus units running firmware version 5.0 or higher. Units with firmware between V3.9 and V4.6 should update to V4.7. Units with firmware prior to 3.9 must be returned to factory for a hardware upgrade before they can be upgraded to any firmware release of version 3.9 or higher. The firmware version can be determined over the RS232 port with the "ID" command

NEW FEATURES: None

CHANGES: None

CORRECTIONS: 1. Properly initialize the VRAM

DATE of RELEASE 6 September 2001
